



Clinic Framing - South Elevation



Clinic Framing - South Elevation



Clinic Framing - West Elevation



Clinic Framing - North West Elevation



Clinic Framing - Garage End



Water line valve box location - will conflict with vehicle traffic.





Crawlspace - Some mold present on underside of joists.



Crawlspace - Fans installed to aid in air circulation



Upper Eave Framing - Gridline A in process.



West Endwall - Overframed.



Grid M, Grid 6 to 7 - Re-shimming is required to provide solid bearing.



Interior Framing

Interior Shearwall Framing in process.





Foundation Waterproofing - Patch slit in membrane before covering.



Pipe Penetrations - Seal penetrations before backfilling.